

Software history (HTS4561, 4562, 5561, 5562, 5581, 5582, 5591, 5592)

Note:

The filename of the bin file may NOT be necessary the same as the model number.

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version 1.59.00

- Fixed network error during CDDA playback
- Improved compatibility with Smartphone (MyRemote) app
- Some fixes for NetTV services
- Some models unable to wake up at correct source mode

Version 1.58.00

- Improved 3D disc playback performance

Version 1.52.00

- Improved Audio Sync
- Fixed system bugs

Version 1.47.10 MCU V36.05

- Fix auto standby issue
- Fix issue with RWSS5510 Wireless Rear Surround module

Version 1.47.10

- Improved system performance

Version 1.27 MCU V36.01

- Solved wireless speaker volume adjustment issue
- Improved playability

Version 1.27

- Improved User Interface
- Improved playability