

## Software history (MCD1165)

### Note:

- Each release contains all solutions identified in the earlier version.
  - The filename of the upgrade file is a .bin file. The filename may NOT necessary be the same as the model number.
- 

The latest software solves the issues below:

### **MCU version: v14**

- Improve the clock accuracy.

### **MCU version: v13**

- Enhance the equalizer settings.
- Avoid the interference from other Philips remote controls.