

Software history (MCM3150X/78)

The latest software improves the below:

NOTE: Each release contains all solutions identified in the earlier version.

version : CD-V36

- Solve problem with CD playback