

Software/driver information

This Device Manager software is embedded with the latest **firmware version 03.42**. The Device Manager Software helps you to get the latest firmware updates for your player.

Benefits of the firmware upgrade

1. Battery charging bug improvement.
2. Mirror bug improvement.

How can I check the firmware version in my player?

You can check the firmware version in your player in either of the below ways.

1. Launch the Device manager software supplied with the player on your PC.
2. Connect the player with your PC. You will see both the current firmware version in your player and that one on the supporting web site on the interface of the Device Manager software.

IMPORTANT: Make sure your PC is connected to Internet when you check the firmware version in your Player.

How can I upgrade the firmware in my player?

There is no need to download the firmware on your PC. The Philips Device manager will automatically download the latest firmware from the support web site to update your player.

1. Make sure that you have your PC connected to Internet before firmware upgrade.
2. Run the Device Manager Software on your PC. If you do not have the Device manager software installed on your PC yet, please get it from the Software/drivers section on the support web site.
3. Connect your player to the PC and then switch on the player.
4. Click the **Update** button on the interface of the Device Manager software. The upgrade process will continue to download firmware.

If this does not work, please right click the Device Manager Software icon in the task tray to select **Check for Updates**, The software will auto search to download the firmware to finish the updating.

5. Once the upgrade process is completed, click **FINISH** to close the application.
6. Disconnect the player from your PC. Notes: If you can find an USB icon  in the task tray on your PC, just click it to safely remove your player from your PC.

Upgrade History

Ver03.32

- Software handling improvement.

Ver01.02: Initial release

- Further improve on the device boot up time.

- Fixed the beep sound with all button events.
- Fixed the 4 FM preset bug after clear the preset.
- Fine tuned on the volume profile.