Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM63E_2.06 (Date published: 2012-09-12)

- TV does not response to the remote control when you switch to France 24 or Balkan TV channels via Teledünya digital service provider. (Only applicable to country, Turkey)
- Picture freezes and TV does not response to the remote control when you switch to Mezzo channel. (Only applicable to country, Serbia)
- TV has no video after startup when you connected a set-top box (STB) through HDMI. (Only applicable to country, France)
- YouSee channel allocation. (Only applicable to country, Denmark)
- Changed the default [Visual impaired] option from on to off.

TPM63E 2.05 (Date published: 2012-04-20)

- TV turns off and on by itself while watching DI.TV channels. (Only applicable to country, Italy)
- Stofa cable provider option is added to the DVB-C installation cable provider list. (Only applicable to country, Denmark)
- Missing UPC channels. (Only applicable to country, Netherlands)
- Picture freeze when you playback motion jpeg file.
- A different audio is heard on some digital channels. (Only applicable to country, Mauritius)

TPM63E_2.03 (Date published: 2012-03-01)

• Introduction of new product ranges.

TPM63E_2.02 (Date published: 2011-11-28)

IMPORTANT: You're highly recommended to upgrade your TV to this software as it covers major certification.

- TV turns off and on by itself while watching channel NT1. (Only applicable to country, France)
- Digital service provider selection is provided in the channel installation menu. (Only applicable to country, Denmark)

TPM63E_2.00 (Date published: 2011-09-02)

• Initial production software.