

## Software history

### Philips 2K20 32PHS6605 & 68x5 & 6905 - range

#### **TPM207E\_202.003.236.001– Date: 2022/06/01**

- Improvements for system stability, reboots
- Fix for Netflix, YT and Prime video playback issue

#### **TPM207E\_202.003.228.001– Date: 2022/03/07**

- Improvements for system stability
- General improvements

#### **TPM207E\_202.003.188.011– Date: 2021/10/18**

- Improvements for WiFi connection issue
- Improvements for system stability
- Fixed HDMI A/V signal via Vodafone STB
- General improvements

#### **TPM207E\_202.003.181.001– Date: 2021/08/09**

- Solutions for playback issues in local VoD services (TV2 Play, NPO Start , Viaplay, OTTPLAYER, M7)
- Improvements for system stability
- General improvements

#### **TPM207E\_202.003.116.011– Date: 2021/04/06**

- Solutions for playback issues in local VoD services (Divan TV, All4 + My5)
- Fixed Slovenian SRT subtitles
- Fixed A/V signal after restarting the HDMI source
- Improvements for system stability
- General improvements

#### **TPM207E\_202.003.085.001– Date: 2021/01/26**

- Improvements for system stability
- Solutions for playback issues in local VoD services (Cmore and Bloomberg)
- General improvements

#### **TPM207E\_202.003.043.011– Date: 2020/12/08**

- Improvements for system stability
- Fix for Netherlands app "NPO Start"
- General improvements

#### **TPM207E\_202.002.238.011– Date: 2020/09/16**

- Initial firmware for 6905 series
- General improvements

#### **TPM207E\_202.002.186.011– Date: 2020/08/01**

- Mediastate Law compliance
- General improvements

#### **TPM207E\_202.002.078.011– Date: 2020/06/16**

- Initial version for /62 CTN

- General improvements

**TPM207E\_202.002.026.011– Date: 2020/04/16**

- Initial firmware for the 2K20 32PHS6605 & 68x5 range