

Software History

NOTE: Each release contains all solutions identified in the earlier version.
The latest software solves the issues below:

TPN1011E_V2.14 (*Date published: 2014-06-10*)

- Issue fix: [Estonia] cracking sound for ATV.
- Issue fix: Picture drops.
- Issue fix: [Austria] UPC jumping channel by itself.
- Issue fix: [Germany] DVB-C loss of all digital services after a night in standby.
- Issue fix: [Italy] channel loss.
- Issue fix: [Portugal] DVB-T reboots sporadically.
- Issue fix: TV cannot re-order in DVB-S.

TPN1011E_V2.13 (*Date published: 2014-03-18*)

- Issue fix: Character set for Cyrillic.
- Issue fix: Sync 2K13 set solution of startup reboot issue.
- Issue fix: Sync 2K13 set DVB-T Modena reboot issue when channel scan in Italy.

TPN1011E_V2.12 (*Date published: 2014-03-03*)

- Issue fix: Field reboots issue.

TPN1011E_V2.11 (*Date published: 2014-02-11*)

- Add multimedia player new feature: character set.
- Issue fix: DVB - T and DVB - C channel sorting at Slovenia.
- Issue fix: Digital channel default value at Slovenia.
- Issue fix: France simulcast
- Issue fix: DVB - T channel scan hand-up in Italy Varedo area.

TPN1011E_V2.09 (*Date published: 2013-11-11*)

- DVB-C HD channel & UPC broadcasting mosaic issue at Netherland.
- Add Ziggo icon for country Netherland.
- Remove Micro Dimming item from OSD UI.
- Polish Translation error.

TPN1011E_V2.02 (*Date published: 2013-08-31*)

- Initial production software for H-models.