

Software history

Philips 2K21 75x6 - ranges

TPN216E _ 216.002.194.021– Date: 2022/09/14

- Solution for distorted picture on HDMI

TPN216E _ 216.002.194.011– Date: 2022/08/22

- Solution for distorted picture on HDMI STB (Slovenia)
- Improvements for OTT Playback
- Solution for flashing picture in game mode

TPN216E _ 216.002.182.011– Date: 2022/03/31

- Improvements TXT in Turkey
- Improvements for Wifi connection
- Solution for channel installation in Russia
- Improvements for Youtube Playback
- Solution for fast forward during streaming video
- Solution for repeated on screen messages

TPN216E _ 216.002.100.041– Date: 2021/11/23

- Solution for start-up behaviour for dedicated HDMI sources

TPN216E _ 216.002.100.031– Date: 2021/09/27

- More support for panel diversity
- General improvements

TPN216E _ 216.002.100.011– Date: 2021/08/09

- Improvements for transitional phenomenon source switching
- General improvements

TPN216E _ 216.002.023.111– Date: 2021/06/07

- Initial firmware for the 55PUS75x6/12

TPN216E _ 216.002.023.091– Date: 2021/05/12

- Initial firmware for the 43PUS75x6 and 50PUS75x6