

## Software history – Philips 2K21 85x6/9006/9206/9636/OLED706/OLED8x6/OLED936 ranges

### **TPM211EA\_001.001.233.005– Date: 2021/09/10**

- Support for HD+ Operator application for Germany
- Improvements for start-up issues (no picture after startup)
- Improvements for stability issues (reboots, freezes, black picture)
- Improvements for Picture Quality

### **TPM211EA\_001.001.212.206– Date: 2021/08/20**

- SW update for all series
- Fix for no picture on HDMI PS4
- Improvements for audio drops/loss on HDMI, TV speakers
- Improvements for channel management, empty channel list, loss of channels
- Improvements for Picture Quality

### **TPM211EA\_001.001.170.007– Date: 2021/07/16**

- Update SW for the 2K21 9206 series

### **TPM211EA\_001.001.170.006– Date: 2021/07/12**

- Initial SW for the 2K21 9206 series

### **TPM211EA\_001.001.170.005– Date: 2021/07/08**

- Initial SW for the 2K21 77OLED806 and 9636 series

### **TPM211EA\_001.001.170.004– Date: 2021/06/30**

- Initial SW for the 2K21 OLED8x6 and 9605 series
- Fix for sound heard from soundbar while TV in standby
- Fix for HBO
- Fix for distorted sound with Dolby Atmos
- Improvement for audio drops/audio loss
- Improvement for DVBS wrong channel list updates
- Improvement for casting
- Improvement for lipsync
- Improvements for stability issues (no startup, reboot, freezes)
- Improvements for TV Guide

### **TPM211EA\_001.001.113.216– Date: 2021/05/12**

- Initial SW for the 2K21 OLED706 (excl 70”) series

### **TPM211EA\_001.001.113.209– Date: 2021/04/29**

- Initial SW for the 2K21 85x6/9006 series