

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPN206E_203.002.168.011 *(Date published: 2021-07-21)*

- "DOLBY ATMOS" icon display when playback Netflix ATMOS movie with Stereo.
- Solution greenish/pinkish picture while in monitor playback.
- Solution vertical lines during VoD/HbbTV Playback
- Solution for no sound in standby
- Solution for no picture at start-up
- General improvements

TPN206E_203.002.086.011 *(Date published: 2020-12-23)*

- Screen will black when photo play finished via USB stick.
- IP pull download process improved.

TPN206E_203.002.069.011 *(Date published: 2020-08-25)*

- TV performance improved.

TPN206E_203.002.058.001 *(Date published: 2020-07-15)*

- Initial production software.