

Software history – Philips 2K19 65x4/67x4/6804/6814/OLED754 ranges

TPM196E_091.002.078.253– Date: 2019/10/16

- Fix for missing page in Turksat scan
- Fix for “Philips SmartTV server not found”
- Support for new Freenet SMiT CI+1.4/ECP CAM

TPM196E_091.002.078.231– Date: 2019/08/27

- Improvement for Rakuten TV performance
- Improvements for start-up behaviour after standby

TPM196E_091.002.078.171– Date: 2019/07/31

- Initial SW for OLED754 range
- Fix for wrong channel bar information
- Fix for KRS DVBC scanning time too long
- Improvements for hang-up, no reaction to RC, stuck after startup
- Improvements for network connectivity
- Improvements for UI
- Improvement for power consumption

TPM196E_091.002.078.111– Date: 2019/07/15

- Initial SW for Alexa 6814 range

TPM196E_091.002.007.141– Date: 2019/06/27

- Enables Rakuten TV App
- Fix for TV hangup on USB loading photo filter

TPM196E_091.002.007.121– Date: 2019/06/21

- Fix for TV stuck
- Fix for home menu auto closes
- Improvement for no reaction to remote control
- Improvement for Rakuten TV performance
- Improvement for Wifi loss and no network connection

TPM196E_091.002.041.051– Date: 2019/06/06

- Released for UK only, supporting FreeView Play

TPM196E_091.002.007.091– Date: 2019/05/24

- Fix for Freenet installation taking too long
- Fix for set not going to standby
- Fix for Auto wake-up
- Improvement for Rakuten TV performance
- Improvement for USB stability
- Improvement for Wifi loss
- Improvement for no response to RC commands

TPM196E_091.002.007.051– Date: 2019/04/18

- Initial SW for the 2K19 65x4/67x4/6804 ranges

