Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM215HC_001.001.113.000 (Date published: 2021-11-25)

- UI translation correction.
- General system improvement

TPM215HC_001.001.027.003 (Date published: 2021-09-17)

• General system improvement

TPM215HC_001.000.221.004 (Date published: 2021-06-10)

• Initial production software.