

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM211EA_001.002.114.205 *(Date published: 2022-05-09)*

- Fix for Hue light not showing correctly.
- Fix for TV reboot when wifi is connected.

TPM211EA_001.002.095.001 *(Date published: 2022-01-24)*

- Fix for vertical line seen on the right side of the screen eg. OLED screensaver
- Fix for Calman color calibration functionality
- Fix ambilight won't change the color or auto turn on
- Improvements for picture quality
 - Flickering, loss of details, frame drops
 - shadows around moving objects
- Fix for no audio on HDMI eARC
- Fix for audio loss on HDMI eARC
- Fix for auto-wake up due to IR interferences
- Fix for a wrong gradation of the bottom ambilight bar
- Fix for crash in settings menu
- Fix for sound settings not stored or not reset
- Prevention for TV going to factory mode unwanted
- Support for AppleTV pre-installation
- Other general system improvements

TPM211EA_001.001.250.200 *(Date published: 2021-10-15)*

- TV has sound but no picture.
- General system improvement

TPM211EA_001.001.230.001 *(Date published: 2021-08-10)*

- Initial production software.