



Mechanical Drawing



Input/Output Terminals



- ① **AC IN**
AC power input.
- ② **MAIN POWER SWITCH**
Main power on/off switch.
- ③ **HDMI IN**
HDMI video/audio input.
- ④ **DVI IN**
DVI-D video input.
- ⑤ **RJ-45**
LAN control function for the use of remote control signal from control center.
- ⑥ **VGA IN (D-Sub)**
VGA video input.
- ⑦ **COMPONENT IN (RCA)**
Component YPbPr video source input.
- ⑧ **AUDIO IN (RCA)**
Audio input from external AV device.
- ⑨ **AUDIO OUT (RCA)**
Audio signal output to connect your external AV device.
- ⑩ **AUDIO IN (3.5mm)**
Audio input from your PC.
- ⑪ **SPDIF OUT**
Digital audio signal output to connect your external AV device.
- ⑫ **IR OUT / ⑬ IR IN (3.5 mm)**
IR signal output/input for the loop-through function.
- ⑭ **RS232C OUT / ⑮ RS232C IN (2.5 mm)**
RS232C network output/input for the loop-through function.
- ⑯ **USB PORT**
Connect your UBS storage device.



© 2013 Koninklijke Philips N.V. All Rights reserved.

Specifications are subject to change without notice.
Trademarks are the property of Koninklijke Philips
N.V. or their respective owners.

PCSM023-121912EN