

Software history (BDP2285)

The latest software improves the below:

NOTE: Each release contains all solutions identified in the earlier version.

Note:

The filename of the bin file may NOT necessarily be the same as the model number.

Version: v1.53(BDP2285 all versions)

- New feature of clearing cookies when there is YouTube playback problem. To do this, follow the steps below:
 - 1) Press [HOME] on the remote control to enter home menu.
 - 2) Within 6 seconds, press [8], [5], [2], [0] buttons on the remote control.

Version: v1.52(BDP2285/12, /05, /51, /55, /79, /96, /98, /F8)

- Improved Netflix performance.
- Improved Wi-Fi performance.

Version: 1.45(BDP2285/F7)

- Improve playback performance
- Netflix improvement

Version: v1.35(BDP2285 all versions)

- Reduced standby time.

Version: 1.21(BDP2285)

- Improve upgrade performance
- Improved Miracast performance (except for the F8& F7 version)
- Improved Targeticket issue