

## Software history (BDP7750)

### Note:

- Each release contains all solutions identified in the earlier version.
  - The filename of the upgrade file (\*.bin) is [BDP7750.bin](#).
  - After you download the upgrade file, extract (upzip) it to a folder. Copy the [extracted folder \(UPG\) with the firmware file](#) inside to the [root directory](#) of a USB flash drive.
- 

### The latest software solves the issues below:

#### **Version 1.37**

- To ensure smoothness of SmartTV performance and improve compatibility.

#### **Version 1.3**

- Reduced auto standby time
- Remove Skype from Applications

#### **Version 1.26**

- Improvement on USB keyboards
- Fixed hang up issue in some operations

#### **Version 1.20**

- Improves Miracast connectivity between Netgear routers and Samsung and MI2A mobile phones.
- Improved response times for Miracast related operation.
- New playback layout and features for Youtube application in SmartTV.
- Improved stability of Youtube streaming playback.
- Resolves an issue where the BDP can only display the 1st 100 folders from a DLNA server.