

Firmware history of BM60

MCU v077; Wi-Fi FW v0204

- General bug fixes
- Enhanced Izzylink connection among speakers
- Multi-pair performance improvements
- Enhanced Bluetooth connection and user interface