

Software history (BTB7150)

Note:

- Each release contains all solutions identified in the earlier version.
 - The filename of the upgrade file is a .bin file . The filename may NOT necessary be the same as the model number.
 - After you download the upgrade file, extract (unzip) it to a known space on PC. Copy the firmware file without rename inside to the root directory of a USB flash drive.
 - After updating the device, some settings might be erased. Please refer to the user manual for the set-up after updating the device.
-

The latest software solves the issues below:

MCU version: v42

- Fix the Bluetooth connectivity issue for some devices

Device version v1A26

- Fix the issue of FM station jumped to preset # 1 suddenly

Reminder: Both v42 and v1A26 have different upgrade instructions, please follow the "Installation instructions" carefully.