

Software history (BTM1360)

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version 28 : (BTM1360/12, /55, /61,/85, /96)

- Solve the issue about gap between tracks during CD playback.

Version 26: (BTM1360/12, /55)

- Solve problem with CD playback.