

Software history (BTM2180/37)

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version 22:

- Solve the issue about gap between tracks during CD playback.

Version 20:

- Solve problem with CD playback