## Software history (BTM2180/12, /61, /85)

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

## Version 26:

Solve the issue about gap between tracks during CD playback

## Version 24:

• Solve problem with CD playback