

## **Software history (DCB2070)**

The latest software improves the below:

**NOTE:** Each release contains all solutions identified in the earlier version.

### **System Software Version: v31 (Apr-2013)**

- Improve playability of some content-protected disc.

### **MCU firmware Version “dab- sermmi- FS2027- 0000- 0359- V4.2.11.38059-1B19” (Aug-2012)**

- Resolve the DAB time synchronization issue.

### **System Software Version: v30 (Aug-2012)**

- Resolve the DAB time synchronization issue.

### **System Software Version: v28 (Mar-2012)**

- Resolve the wrong time in standby mode.