

## Software history (HTB3525B/F7)

### Note:

- The filename of the bin file may NOT necessarily be the same as the model number.
  - Each release contains all solutions identified in the earlier version.
  - After updating the device, some settings such as HDMI-CEC might be erased. Refer to the user manual for the set-up after updating the device.
- 

### The latest software solves the issues below:

#### **Version V1.18.01**

- Fix bugs during start up
- Improve overall sound performance
- Shorten system wake up time
- Online service update – Target Ticket app is added

#### **Version V1.17.09**

- Keep at ARC connection after power off player

Note: After upgrading with the latest firmware, disconnect the device from power supply. Wait for a few seconds and then reconnect to power supply.