

Software history_HTB7530_7560_7590

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version V1.16.06 (MCU V10)

- Removal of Skype service
- Fixed security vulnerability in web browser function
- Fixed DLNA issue where set will freeze when scrolling long media list
- Fixed loss of FM audio during wakeup

Version V1.16.02 (MCU V16)

- Fixed HTB no response to RC if used as HDMI ARC
- HDMI CEC related fixes

Version V1.16.01 (MCU V15.07)

- Bug fixes
- In compliance with new AACs requirements, Blu-ray playback via CVBS output is now disabled. Please watch your Blu-ray movies via HDMI connection.

Version V1.14.00 (MCU V15.07)

- Fixed blue screen issue after change source to DISC mode
- Fixed DISC source switching issue with DISC button on RC
- Fixed issue that cause system corruption over extended operation

Version V1.13.30 (MCU V15.07)

- Fixed Skype crash issues
- Bug fixes

Version V1.13.30 (MCU V15.07)

- Fixed certain sound-related issues

Version V1.09.01 (MCU15.05)

- Tuner fix

Version V1.09.01

- SimplyShare Functionality Improvements
- Sound enhancement