

Software history (HTB7250, 7255, 9225, 9245)

Note:

- The filename of the bin file may NOT necessarily be the same as the model number.
 - Each release contains all solutions identified in the earlier version.
 - After updating the device, some settings such as HDMI-CEC might be erased. It is advised to perform a factory default reset after update
Refer to the user manual for the set-up after updating the device.
-

The latest software solves the issues below:

Version V1.10.00:

- Fixed random volume spike issue in disc playback
- Fixed Youtube-related playback issues
- Fixed HDMI CEC issue where product cannot wake up by TV
- In compliance with new AAC3 requirements, Blu-ray playback via CVBS output is now disabled. Please watch your Blu-ray movies via HDMI connection

Version V1.06.03:

- Fixed personal sound setting retention issue
- Adjust remote control responding issue.

Version V1.06.01:

- Software upgrade process improvement.
- Fix the hang up during wake up from standby.
- Fix sound issue when the source is changed from Skype to others.
- Fix sound issue when changing the source to iPod mode.
- For HTB9225 and HTB9245: Fix a software bug when there is another player connect to any one of the HDMI-IN of the Home Theater System and changes HDMI resolution.