

Software history (HTL4110B except /F7 and HTL4111B/12)

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version 55

- Improved HDMI ARC compatibility
- Improved sound performance
- Reduced auto standby time according to ErP3 requirement

Version 51

- Shorten the time of start up after disconnect the power
- Improved the noise issue at strong bass setting

Version 50

- Increase the loudness at ARC connection
- Fixed the issue of not turned on by some TV at ARC connection

Remarks: The upgrade procedures are changed after version 43, please follow the procedures of upgrade instructions to complete the upgrade.

Version 43

- Improve HDMI ARC performance
- Support NTFS file format
- Improve Easylink performance
- Improve intermittent no sound from optical input after start-up

Version 26

- Improve HDMI ARC performance
- Improve USB playback performance