

Software history_HTL7140

Note: The filename of the bin file may NOT necessary be the same as the model number.

The latest software solves the issues below:

Version 31

Local Display version info (will show in following sequence)

- Main Unit (MCU) Version: V31
 - HDMI Repeater (RPT) version: V16
 - TX version: V03
 - Subwoofer RX version: V03
 - Touch Panel Version: 20
-
- Optimised Auto Volume algorithm
 - Fixed AUTO VOLUME setting retention issue
 - Fixed RC_STANDBY key function issue