

Software history (HTS55x3)

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Note: The filename of the bin file may NOT necessary be the same as the model number.

Note: This firmware is meant for HTS55x3 with serial number starting with PT2Bxxxxxxxx

Version V1.13.30 (MCU V9.10)

- Fixed certain sound-related issues