

Software history

The latest software improves the below:

NOTE: Each release contains all solutions identified in the earlier version.

For MCM2300/12, /55, /77, /79, /93, /96 (v18)

- Solve problem with CD playback

For MCM2150/12, /55, /77, /05, /98 (v27)

- Solve problem with CD playback

For BTB2315/12 (CD v18; MCU v29)

- Solve problem with CD playback

For BTM3160/12 (v07)

- Solve problem with CD playback

For BTM2335/12 (v14)

- Solve problem with CD playback